

Topside Error Codes - 2020+

The Spas firmware is designed to detect most errors, and then the CPU will provide feedback for the user on the topside, mobile application and by flashing the lights on the spa.

ER 02	HL	Heater Over Temp
ER 03	HL(F)	Spa over temp
ER 04	Prr	SPA Temp probe
ER 05	HL	Spa High Limit
ER 07	FP	Freeze Protect
ER 08	Ph	pH High
ER 09	Hd	Heater probe disconnected
ER 10	HPt	Heater probe test failed
ER 11	SB-CE	SpaBoy Comms Error
ER 13	H-wo-s	Heater way above Spa
ER 14	orp_nr	Orp not responding to production
ER 15	Ph_L	PH low (less than 6.5)